

NOTE TO FILE

From: K. Rodriguez

11/29/10

Site Name: Flying B 29

UST ID: 10589

On October 18, 2010, I called Gary Bains to let him know the CP tests provided by Kevin Wilkerson were not acceptable. Mr. Wilkerson showed both galvanic and impressed current tests passing and the forms were not filled out correctly. A CP audit done at this facility indicated both systems were not adequately providing protection to the UST system.

On October 20th, Arthur Buchan provided Kevin Wilkerson with his testing results and also explained that the forms were not filled out properly. He stated that the CP systems must be tested correctly or face possible enforcement.

On November 29th, I contacted Mr. Bains. I have not received updated/edited CP testing checklists for this site. Since I had already provided him an extra month to submit the form (they were due November 1), I gave him until Friday (Dec. 3rd) to submit new checklists. I told him that if I didn't receive them by the 3rd, I would be sending out a \$200 penalty on December 6th. He said that sounded fair.

I called Mr. Bains right back about another site and he was speaking with Mr. Wilkerson. Mr. Bains put us on a three-way phone call. Mr. Wilkerson planned to re-test the CP systems on November 30th and he would fax information for both sites.

11/30 Mr. Wilkerson called to say the ⁱⁿpasses are too bad & he could not drive to Ellensburg. He will try again later in the week & keep me updated.

Flying B 29
UST 10-89
Kubla, City

Rodriguez, Krystal (ECY)

From: Buchan, Arthur (ECY)
Sent: Wednesday, October 20, 2010 10:11 AM
To: Nes inc
Cc: Rodriguez, Krystal (ECY); Monahan, Mary (ECY)
Subject: Flying B (Ellensburg)



CP Audit
(#10589[G]).doc



CP Audit
(#10589[IC]).doc

Kevin,

I have attached the results from my CP Audit for the above site. Both the Galvanic and the Impressed current systems at this site failed my audit. Krystal forwarded your results for this site to me and you indicated that they passed. The checklists that were forwarded to me from Krystal were not filled out correctly, and therefore not acceptable per Washington State standards. If you would like to discuss this, I would be more than willing to meet with you.

My recommendation to Krystal is to inform the owner that the checklists were filled out improperly and to not accept the testing paperwork provided under:

WAC 173-360-320(2)(b) Inspection criteria. The criteria that are used to determine that cathodic protection is adequate as required by this section shall be in accordance with a code of practice developed by a nationally recognized association. Note: NACE Standard RP-0285 maybe used to comply with subsection (2)(b) of this section. And;

WAC 173-360-630 – Responsibilities of Service Providers. A checklist must be completed for each regulated activity performed. (Checklist was filled out improperly)

If Krystal decides to agree with my recommendation, the end result would be that the owner will still need to have the cathodic protection system tested correctly, or face possible enforcement.

Please contact me if you have any questions.

Arthur Buchan
Washington Department of Ecology
Northwest Regional Office
3190 160th Ave SE
Bellevue, WA 98008-5452
Phone: (425) 649-7149
www.ecy.wa.gov/programs/tcp/ust-lust/tanks.html

SHORT STOP LLC
1307 N. DOLLARWAY RD.
ELLENSBURG, WA 98926

Phone Number 509-925-9270
Fax Number 509-925-9271

Email : flyingb27@yahoo.com

FAX TRANSMITTAL FORM

To: Department of Ecology
Name: Attn, Krystal Rodriguez
CC:
Phone:
Fax:

From: Gary Bains- Short Stop LLC
Date Sent: 10/15/2010

Number of Pages: 7-including cover sheet

Attn: Krystal Rodriguez :
Underground Storage Tank Inspector

Thank you,

Gary Bains
Flying B

RECEIVED

OCT 15 2010

DEPARTMENT OF ECOLOGY - CENTRAL REGIONAL OFFICE

